


Safety Communication

Risk of Operating light detaches

Device/ Product Description:	Operating light	
Brand Name:	MAQUET HLX 2004-5 DF, HLX 3004-5 DF, and XTEN DF	
Lot numbers/Serials:	Spring arm part number	Up to Ondal SN
	ARD569002996	11102751560
	ARD569002998	49060043398
	ARD569002999	4306038616
	ARD567910901	35060032600
	ARD567910910	44060038859
	ARD567801093	36060033055
	ARD567801094	45060039322
Manufacturer:	Getinge Disinfection AB	
Problem:	ONDAL Acrobat 2000 spring arms manufactured between January 2004 and December 2006 may break due to a crack in the metal of the spring arms that may result in risk that the light cupola detaches.	
Recommendation/Actions:	<ol style="list-style-type: none"> 1- Check if your facility is affected or not (you could use the “List of potentially affected devices” in the link below. 2- If your facility is affected, contact the authorized representative to replace the affected parts <p>You can find more information and recommendations from (HERE).</p>	



You **should** be aware of the mentioned risks in the notice and **contact** the Authorized Representative of your product for corrective action.

Healthcare Professionals should **report any adverse events** suspected to be associated with affected devices above (or other Medical Devices) to:

[National Center for Medical Devices Reporting.](#)

Medical Devices Sector
Saudi Food and Drug Authority
Postal Address: Saudi Arabia - Saudi Food and Drug Authority
4904 northern ring branch rd - Hitteen Dist.
RIYADH 13513 - 7148
Tel: +966 (11) 2038222 Ext: 2995, 2952
Fax: +966 (11) 2757245

Or

[Saudi Vigilance](#)

For latest published FSCAs, please visit ([NCMDR Website](#))

Sincerely,
NCMDR Team