


Safety Communication

رسالة سلامة

**Safety cap attached to needles
within the EZ-IO needle sets may become dislodged**

Device/ Product Description:	Intraosseous vascular access needle sets
Brand:	Arrow EZ-IO
Lot/Serial Number:	9018P-EE-005; 9018P-EU-005; 9018P-ME-005; 9018P-NO-005; 9018P-VC-005; 9001P-EE-005; 9001P-EU-005; 9001P-ME-005; 9001P-NO-005; 9001P-VC-005; 9079P-EE-005; 9079P-EU-005; 9079P-ME-005; 9079P-NO-005; 9079P-VC-005
Manufacturer:	Teleflex Medical
Problem:	Safety cap attached to needles within the needle sets may become dislodged exposing the needle and potentially causing the needle to protrude through the packaging. If this issue is not detected, the immediate risk of exposure to the affected devices is needle stick injury to the clinician or healthcare professional. In addition, a puncture of the packaging may compromise the sterility of the needle.
Recommendation/Actions:	<ol style="list-style-type: none"> 1- Visually inspect the product. 2- Dispose of product If you identify codes/lots as defective 3- Pass on this notice to all persons who need to be aware within your organization <p>for more information, please click here</p>
Devices/Products photo:	

Authorized Representative Details	AR name:	First United Medical Company
	Assigned Contact Person:	Khalid Mohammad AlFuhaid
	Mobile/Phone:	0544081009
	Email:	shivappa.gowda@fumedco.net

