

Date: 25 April 2022

Reference Number: SG-2204-389-H

Medical Devices Sector  
National Center for Medical Devices Reporting


رسالة سلامة  
**Safety Communication**

To: Healthcare providers	إلى: مقدمي الرعاية الصحية
--------------------------	---------------------------

<b>Title:</b>	Risk of air embolism	العنوان:
<b>Medical Device Description</b>	BD Plastipak 50mL Syringe with Luer-Lok Tip	اسم ووصف الجهاز/المستلزم الطبي:
<b>Manufacturer:</b>	Becton Dickinson & Co. (BD)	اسم المصنع:
<b>Authorized Representative</b>	Becton Dickinson B.V.	الممثل المعتمد

<b>Medical Devices Marketing Authorization (MDMA)</b>	GHTF-2020-0178	إذن التسويق:
<b>Potential /Associated Risks</b>	A potential for air ingress into the syringe when the barrel is damaged and the syringe is used in an infusion pump.	المخاطر المحتملة المرتبطة بالجهاز أو المستلزم الطبي
<b>Recommendations</b>	<ul style="list-style-type: none"> <li>Follow Good Clinical Practice regarding the inspection of medical devices for damage, integrity and function before, during, and after use. Devices found with damage should not be used.</li> <li>If you identify syringe damage, report as a complaint as per your normal process.</li> <li>Notify all users about this safety communication</li> </ul>	التوصيات

<b>Authorized Representative Details:</b>	AR name:	Becton Dickinson BV Saudi Limited Company	معلومات الممثل المعتمد:
	Assigned Contact Person:	Nawaf Mansour Alsalmi	
	Mobile/Phone:	0566898822	
	Email:	<a href="mailto:GMB-SAU-REGULATORY@bd.com">GMB-SAU-REGULATORY@bd.com</a>	
<b>Related Links</b>	<a href="#">Here</a>		روابط ذات صلة

<b>For Reporting:</b>	 مركز الاتصال الموحد		 تيقظ Saudi Vigilance	للإبلاغ:
-----------------------	--	---	---	----------